


BACK OF MOTOR
6.0L Ford Power Stroke

ICP Sensor
Location



FLEXPLATE